



## Honda de la Capitale

1507 boulevard Pie XI sud  
Quebec (Secteur Val-Belair)  
G3K 1Y1

1 581 703-8161

### Make / Model

Honda CRV LX

### Year

2018

### Mileage indicated / actual\*

51,889 km

### Transmission

### Drive Type

FWD

### Engine

4 cyl. / 1.5 liters

### Fuel Type

unleaded

### Serial number

### Stock number

U3578



### EQUIPMENTS

Air conditioning, Cruise control, Heated Driver Seat, Heated mirrors, Power locks, Power Mirrors, Power sliding doors, Power steering, Power windows, Remote Entry, Remote starter, Adjustable steering wheel, ABS Brakes, Driver airbag, Passenger airbag, Rear defrost, Alarm system, Lateral airbags, Stability control, Traction control, Intermittent wipers, Tinted windows, Two-toned paint, AM/FM stereo, Bluetooth, MP3 Player, Bucket seats, Split folding rear seats, Stow'n Go, Tachometer, Reverse camera, Child safety locks, Climate control, Driver vanity mirror, Passenger vanity mirror, Pass-Through rear seat, Split bench seat, Tire pressure monitoring system, Rear head air bag, Front floor mats, Anti-theft system, Brake assist, Auxiliary audio input, Onboard computer, Keyless entry, Auto-on headlights, Keyless start, Audio steering controls, USB Port, Back windshield wiper

### SALE PRICE

**\$25,477**

Plus tax.

### Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for :

The dealer will supply upon request the name and phone number of the last owner.

### Category

Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:

Legal warranty : C - 1 month - 1700 KM

As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:

A ☐ 6 months or 10 000 km B ☐ 3 months or 5 000 km C ☐ 1 month or 1 700 km

D ☐ Good working (subject to 37, 38 L.P.C.) E ☐ No warranty

### Repairs done and mechanical verification certificate

The following repairs have been done on this vehicle since the dealer's possession.

If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.

### Comments

### Optional repairs

The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Date : \_\_\_\_\_ Signature : \_\_\_\_\_

autoExpert.ca

Sticker # : 7901868