

bag, Front floor mats, Brake

Date :

Honda de la Capitale

1507 boulevard Pie XI sud Quebec (Secteur Val-Belair) G3K 1Y1

1 581 703-8161

Make / Model	
Mazda CX5 GT	
Year	Mileage indicated / actual*
2022	10,642 km
Transmission	Drive Type
automatic	AWD
Engine	Fuel Type
4 cyl. / 2.5 liters	unleaded
Serial number	Stock number
	35660A



EQUIPMENTS

Adaptive cruise control, Air conditioning, Cruise control, Heated Driver Seat, Heated mirrors, Memory seats, Power locks, Power Mirrors, Power driver seat, Power sliding doors, Power steering, Power windows, Remote Entry, Adjustable steering wheel, Dual zone A/C, Heated steering, Heated back seats, ABS Brakes, Driver airbag, Passenger airbag, Rear defrost, Alarm system, Lateral airbags, Stability control, Traction control, Intermittent wipers, Rain sensor wipers, Tinted windows, Sunroof, Two-toned paint, AM/FM stereo, Bluetooth, MP3 Player, Satellite radio, Bucket seats, Split folding rear seats, Stow'n Go, Head up display, Tachometer, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Pass-Through rear seat, Leather seats, Split bench seat, Power passenger seat, Tire pressure monitoring system, Rear head air

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

	Category	
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:	
Legal warranty : A - 6 month - 10000 KM	A ☐ 6 months or ☐ 3 months or ☐ 1 month or	
	7 10 000 km 5 5 000 km 5 1 700 km	
	D Good working E No warranty	
Repairs done and mechanical verification certificate Comments		
The following repairs have been done on this vehicle since the dealer's possession.		
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.		
Optional repairs		
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below:		
-		

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

7975756